



CONTRACTOR FIELD REPORT

Jobsite summary and daily crew timeline

PROJECT IDENTIFICATION

Report ID	LUSA-2026-1042	Service Date	10/08/2026
Contractor	Example Roofing Co.	Crew	Crew 07
Jobsite	123 Example Lane, Dallas, TX		
Scope	Residential asphalt shingle tear-off and replacement		

CREW ATTENDANCE / PRODUCTION LOG

Crew arrived	7:04 AM
Work started	7:32 AM
Work finished	4:38 PM
Crew departed jobsite	5:06 PM

WEATHER CONDITIONS

Conditions	Partly cloudy	Temperature	68-84 F
Wind	SW 6-11 mph	Precipitation	None observed
Work impact	No weather delays reported		

DAILY SUMMARY

Existing roof covering removed; substrate inspected and roof system installed.
Potential supplement conditions documented separately for contractor review.
Final cleanup, magnetic nail sweep and departure documented.

REPORT PURPOSE

Production verification, photo evidence and potential insurance supplement review.



CONTRACTOR FIELD REPORT

Possible insurance supplement observations

FIELD OBSERVATIONS / PHOTO INDEX

Conditions below are examples, not approved supplements or coverage determinations.

PHOTO

01

Double layer shingle removal

Existing second shingle layer visible during tear-off.

Evidence: close-up + contextual wide shot

PHOTO

02

Double layer underlayment removal

Two distinct underlayment layers exposed and removed.

Evidence: close-up + contextual wide shot

PHOTO

03

Roof deck renail

Deck fastening documented prior to new underlayment.

Evidence: close-up + contextual wide shot

PHOTO

04

Roof flashings replaced

Existing flashing removed; new flashing installed.

Evidence: close-up + contextual wide shot

PHOTO

05

Gutter pins through drip edge

Fasteners penetrating drip edge documented.

Evidence: close-up + contextual wide shot

PHOTO

06

Roof pitch measurements - all slopes

Standard roofing pitch gauge shown at each roof plane.

Evidence: close-up + contextual wide shot

CONTRACTOR REVIEW REQUIRED

Verify policy, local code, measurements, estimate line items and supporting images.



CONTRACTOR FIELD REPORT

Roof pitch schedule and photo delivery

ROOF PITCH LOG - STANDARD ROOFING PITCH GAUGE

Each roof plane measured independently; sample readings below.

SLOPE	PITCH	GAUGE PHOTO	REFERENCE
Front main	6/12	Captured	P-01
Rear main	6/12	Captured	P-02
Garage	4/12	Captured	P-03
Left hip	7/12	Captured	P-04
Right hip	7/12	Captured	P-05

PHOTO DOCUMENTATION PACKAGE

10

BEFORE PHOTOS

Arrival, pre-existing conditions, protection in place

20

DURING PHOTOS

Tear-off, installation, decking, supplement candidates

YES

COMPLETION PHOTOS

Finished roof, cleanup, debris removal and final site

DELIVERY / SIGN-OFF

Delivered to: Example Roofing Co. | Format: PDF report + labeled image folder

Field verification: Sample crew lead | Status: Submitted for contractor review

Photo slots are illustrative placeholders; no actual jobsite images are represented.